


# Appendix C – Road Traffic Accident Summary 2018 - 2023



# Appendix C – Road Traffic Accident Summary 2018 - 2023

Location 1 – Gainsborough Drive – Opposite junction with Endsleigh Gardens	accident reference	1151820	file reference	
	accident date	2022-03-02	location	GAINSBOROUGH DRIVE NEAR JUNCTION WITH ENDSLEIGH GARDENS, LEAMINGTON SPA
	accident year	2022	accident description	CYCLIST WAS CYCLING TOWARDS SYDENHAM DRIVE WHEN VEHICLE CAME OUT OF ENDSLEIGH GARDEN AND KNOCKED HER OFF HER CYCLE. THE VEHICLE DID NOT STOP, LARGE GREY VEHICLE POSSIBLY HAD Y, 1 OR L IN VRM. APPARENTLY CAMERAS ON ROAD HEADING TOWARDS SYDENHAM DRIVE.
	road name 1	U	other factors	
	road name 2	U	cycle	true
	severity	Slight	power d2w	false
	fatal	0	car taxi	true
	serious	0	minibus	false
	slight	1	lgv	false
	number of vehicles	2	hgv	false
	number of casualties	1	other vehicle	false
	day of week	Wednesday	breath test	false
	accident time	1100	pedestrian	false
	pedestrian crossing human	None within 50 metres	child pedestrian	false
	pedestrian crossing physical	No physical crossing facility within 50 metres	child cycle	false
	light	Daylight	child school	false
	weather	Fine without high winds	rda police	
	surface	Dry	easting	433079
	file		northing	264771

# Appendix C – Road Traffic Accident Summary 2018 - 2023

Location 2 – Gainsborough Drive – by junc with Springwell Road	<table> <tr><td>accident reference</td><td>1107205</td></tr> <tr><td>accident date</td><td>2021-10-29</td></tr> <tr><td>accident year</td><td>2021</td></tr> <tr><td>road name 1</td><td>U</td></tr> <tr><td>road name 2</td><td>U</td></tr> <tr><td>severity</td><td>Slight</td></tr> <tr><td>fatal</td><td>0</td></tr> <tr><td>serious</td><td>0</td></tr> <tr><td>slight</td><td>1</td></tr> <tr><td>number of vehicles</td><td>3</td></tr> <tr><td>number of casualties</td><td>1</td></tr> <tr><td>day of week</td><td>Saturday</td></tr> <tr><td>accident time</td><td>2247</td></tr> <tr><td>pedestrian crossing human</td><td>None within 50 metres</td></tr> <tr><td>pedestrian crossing physical</td><td>No physical crossing facility within 50 metres</td></tr> <tr><td>light</td><td>Dark: street lights present and lit</td></tr> <tr><td>weather</td><td>Fine without high winds</td></tr> <tr><td>surface</td><td>Dry</td></tr> <tr><td>file reference</td><td></td></tr> </table>	accident reference	1107205	accident date	2021-10-29	accident year	2021	road name 1	U	road name 2	U	severity	Slight	fatal	0	serious	0	slight	1	number of vehicles	3	number of casualties	1	day of week	Saturday	accident time	2247	pedestrian crossing human	None within 50 metres	pedestrian crossing physical	No physical crossing facility within 50 metres	light	Dark: street lights present and lit	weather	Fine without high winds	surface	Dry	file reference		<table> <tr><td>location</td><td>GAINSBOROUGH DRIVE NEAR JUNCTION WITH SPRINGWELL ROAD, SYDENHAM</td></tr> <tr><td>accident description</td><td>VEH001 HAS DRIVEN DOWN GAINSBOROUGH DRIVE AND COLLIDED WITH STATIONARY PARKED VEH002. THE FORCE OF THIS HAS PUSHED VEHICLE 2 INTO VEH003. THIS RESULTED IN VEHICLE 1 SUSTAINING EXTENSIVE FRONT NEARSIDE DAMAGE. VEHICLE 2 SUSTAINING REAR OFFSIDE DAMAGE AND FRONT END DAMAGE. VEHICLE 3 SUSTAINING REAR END DAMAGE.</td></tr> <tr><td>other factors</td><td></td></tr> <tr><td>cycle</td><td>false</td></tr> <tr><td>power d2w</td><td>false</td></tr> <tr><td>car taxi</td><td>true</td></tr> <tr><td>minibus</td><td>false</td></tr> <tr><td>lgv</td><td>false</td></tr> <tr><td>hgv</td><td>false</td></tr> <tr><td>other vehicle</td><td>false</td></tr> <tr><td>breath test</td><td>true</td></tr> <tr><td>pedestrian</td><td>false</td></tr> <tr><td>child pedestrian</td><td>false</td></tr> <tr><td>child cycle</td><td>false</td></tr> <tr><td>child school</td><td>false</td></tr> <tr><td>rda police</td><td></td></tr> <tr><td>easting</td><td>433541</td></tr> <tr><td>northing</td><td>264922</td></tr> </table>	location	GAINSBOROUGH DRIVE NEAR JUNCTION WITH SPRINGWELL ROAD, SYDENHAM	accident description	VEH001 HAS DRIVEN DOWN GAINSBOROUGH DRIVE AND COLLIDED WITH STATIONARY PARKED VEH002. THE FORCE OF THIS HAS PUSHED VEHICLE 2 INTO VEH003. THIS RESULTED IN VEHICLE 1 SUSTAINING EXTENSIVE FRONT NEARSIDE DAMAGE. VEHICLE 2 SUSTAINING REAR OFFSIDE DAMAGE AND FRONT END DAMAGE. VEHICLE 3 SUSTAINING REAR END DAMAGE.	other factors		cycle	false	power d2w	false	car taxi	true	minibus	false	lgv	false	hgv	false	other vehicle	false	breath test	true	pedestrian	false	child pedestrian	false	child cycle	false	child school	false	rda police		easting	433541	northing	264922
accident reference	1107205																																																																											
accident date	2021-10-29																																																																											
accident year	2021																																																																											
road name 1	U																																																																											
road name 2	U																																																																											
severity	Slight																																																																											
fatal	0																																																																											
serious	0																																																																											
slight	1																																																																											
number of vehicles	3																																																																											
number of casualties	1																																																																											
day of week	Saturday																																																																											
accident time	2247																																																																											
pedestrian crossing human	None within 50 metres																																																																											
pedestrian crossing physical	No physical crossing facility within 50 metres																																																																											
light	Dark: street lights present and lit																																																																											
weather	Fine without high winds																																																																											
surface	Dry																																																																											
file reference																																																																												
location	GAINSBOROUGH DRIVE NEAR JUNCTION WITH SPRINGWELL ROAD, SYDENHAM																																																																											
accident description	VEH001 HAS DRIVEN DOWN GAINSBOROUGH DRIVE AND COLLIDED WITH STATIONARY PARKED VEH002. THE FORCE OF THIS HAS PUSHED VEHICLE 2 INTO VEH003. THIS RESULTED IN VEHICLE 1 SUSTAINING EXTENSIVE FRONT NEARSIDE DAMAGE. VEHICLE 2 SUSTAINING REAR OFFSIDE DAMAGE AND FRONT END DAMAGE. VEHICLE 3 SUSTAINING REAR END DAMAGE.																																																																											
other factors																																																																												
cycle	false																																																																											
power d2w	false																																																																											
car taxi	true																																																																											
minibus	false																																																																											
lgv	false																																																																											
hgv	false																																																																											
other vehicle	false																																																																											
breath test	true																																																																											
pedestrian	false																																																																											
child pedestrian	false																																																																											
child cycle	false																																																																											
child school	false																																																																											
rda police																																																																												
easting	433541																																																																											
northing	264922																																																																											

# Appendix C – Road Traffic Accident Summary 2018 - 2023

<p>Location 3 – Gainsborough Drive – by Eastwood Close</p>	<p>accident reference 1061227</p> <p>accident date 2021-06-27</p> <p>accident year 2021</p> <p>road name 1 U</p> <p>road name 2 U</p> <p>severity Slight</p> <p>fatal 0</p> <p>serious 0</p> <p>slight 1</p> <p>number of vehicles 2</p> <p>number of casualties 1</p> <p>day of week Monday</p> <p>accident time 1749</p> <p>pedestrian crossing human None within 50 metres</p> <p>pedestrian crossing physical No physical crossing facility within 50 metres</p> <p>light Daylight</p> <p>weather Fine without high winds</p> <p>surface Dry</p> <p>file reference</p>	<p>location GAINSBOROUGH DRIVE, LEAMINGTON AT JUNCTION ACCESS TO CAR PARK FOR EASTWOOD CLOSE</p> <p>accident description V1 IS TRYING TO EXIT A PARKING AREA, HE HAS PULLED UP TO THE GIVE WAY LINE BUT HIS VIEW TO THE RIGHT HAS BEEN BLOCKED DUE TO A PARKED POST OFFICE VAN. V1 HAS TRIED TO LOOK UP THE NEARSIDE OF THE VAN, HAS EDGED FORWARD BUT HAS COLLIDED WITH A PASSING CAR - UNFORTUNATE ACCIDENT</p> <p>other factors</p> <p>cycle false</p> <p>power d2w false</p> <p>car taxi true</p> <p>minibus false</p> <p>lgv false</p> <p>hgv false</p> <p>other vehicle false</p> <p>breath test false</p> <p>pedestrian false</p> <p>child pedestrian false</p> <p>child cycle false</p> <p>child school false</p> <p>rda police</p> <p>easting 433548</p> <p>northing 264834</p>
--	--	--

## Appendix C – Road Traffic Accident Summary 2018 - 2023